

NTSB Identification: ATL81FA080

14 CFR Part 91 General Aviation
Aircraft: PIPER PA-22, registration: N4414A

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1872	81/6/5	CHAPEL HILL,NC	PIPER PA-22	CR-	1	0	0	NONCOMMERCIAL	PRIVATE, AGE 41, 226
	TIME - 0920		N4414A	PX-	0	3	0	PLEASURE/PERSONAL TRANSP	TOTAL HOURS, 163 IN TYPE,
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		NOT INSTRUMENT RATED.
		NAME OF AIRPORT - HORACE WILLIAMS							
		DEPARTURE POINT		INTENDED DESTINATION					
		CHAPEL HILL,NC		OCRACOCKE,NC					
		TYPE OF ACCIDENT		PHASE OF OPERATION					
		STALL: SPIN		TAKEOFF: INITIAL CLIMB					
		PROBABLE CAUSE(S)							
		PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS							
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
		REMARKS- CLIMBED STEEPLY AFTER LIFTOFF.STALL/SPIN WITHIN AIRPORT BOUNDARY.HEAVILY LOADED,BUT WITHIN LIMITS.							

Full narrative is not available

[Aviation Accident & Synopsis Query Page](#)

[Index for June 1981](#) | [Index of months](#) | [Back to result](#)